



Lebanese
Ministry of Agriculture

Funded by



Sweden
Sverige



International
Labour
Organization

Electrical Shock Hazards

Risks:

01

Damaged
wires, plugs,
or tools

Wet conditions
or water
contact

02

Overhead
power
lines

03

Cluttered
work areas

04



How to Stay Safe:




Inspect tools, wires, and
plugs before use




Keep hands, tools,
and cords dry




Only trained electricians
handle repairs



Turn off power before cleaning
or fixing equipment



Keep ladders, hoses, and
metal away from wires



Don't overload
sockets



Keep youth/untrained
workers away